

# FLOW-LINER®

“KEEPS THE POOL OPEN”



Harrisburg Township Park Pool

## Issue

The Harrisburg Township Park District Pool was losing over 3000 gallons of water a day due to their leaking underground pipes.



Flow-Liner® Inversion System

## Solution


A Flow-Liner® certified installer cleaned three lines ranging from 4” to 8” and installed Flow-Liner®’s Cured in Place Pipe Lining System.



Before Flow-Liner® Installation

## Results

The Flow-Liner® installer successfully lined the pipes from the pool to the pump house. The customer was very excited to have the liners installed – and no more 3000-gallon water bills!



After Flow-Liner® Installation

We are pleased to announce another successful project and proudly add



**Harrisburg Township Park District**

to our list of happy and satisfied customers.