

Flow-Liner® EXTENDS PIPES LIFE


“JUST WHAT THE DOCTOR ORDERED”

Cured-In-Place-Pipe Lining



Before Picture
Showing
deteriorated cast
iron pipe bottom

New Canopy and
Concrete Skirt with new
parking lot in the
background



After Pipe was
lined with
Flow-Liner®

Problem: A newly remodeled medical office had a badly deteriorated underground cast iron sewer pipe. In some locations of the cast iron the bottom of the pipe was missing due to excessive deterioration. The pipe was also heavily scaled and had become a drainage issue prior to the medical office's grand opening. The building was previously home to the local Social Security Office for over 40+ years.

Issues: The sewer pipe ran under the “newly paved” asphalt parking lot and the buildings main entrance canopy's concrete skirt. The distance across the parking lot was approx. 165 ft. The Doctor did not want the new asphalt and concrete excavated due to the grand opening being scheduled very soon. Excavation would cause a substantial set-back in the office opening and would generate dust and debris on the newly renovated office's exterior.

Solution: A Certified Flow-Liner® Installer will re-line the main sewer pipe under the parking lot and canopy with the Flow-Liner® Cured-In-Place-Pipe lining system.

Result: The 165 ft. long cast iron sewer pipe was lined successfully. The parking lot and the main entrance canopy's concrete skirt were saved. Flow-Liner® resuscitated the existing pipe and extended its life span by a minimum of 50+ years with its Cured-In-Place-Pipe Lining System.

The Doctor was very happy and made the following comment in his Grand Opening Flyer:

“Special thanks to Flow-Liner's installer for lining the disintegrating outside sewer line from the old Social Security Building to create a “like new” line without any major digging.”

Flow-Liner® is pleased to announce another successful project and add

Southeastern Ohio Urology Associates

To our Roster of Happy Satisfied Customers